## Tech Ops Safety Action Program (T-SAP)

Team Login

Email | Subscribe | Unsubscribe | Print

T-SAP Main

Status: Active Effective Date: 07/21/2014
Facility Information

NAS Category: Equipment: Locations: Fac ID Code:

COMMUNICATION TVS Multiple 48HB

**Event Information** 

Title: .

T-SAP Advisory: TSAP-14-003

Problem: Modifications to a TRACON which included replacing a metal wall that encompassed the Enhanced Terminal

Voice Switch (ETVS) footswitch keying jack resulted in three of five Air Traffic Control TRACON positions

being constantly keyed when a headset/handset was plugged-in.

Symptom: Investigation revealed that the new jacks were installed in undersized holes with missing insulating

bushings, resulting in several jacks shorting to ground through the metal wall and constantly keying

multiple frequencies.

Solution: According to the ETVS manufacturer and site installation documentation, the footswitch jack must be mounted using a manufacturer-supplied jack mounting plate that is part of the manufacturer footswitch

cable assembly. This will allow the footswitch jack to remain insulated from the console or wall to prevent shorting. In addition, if the mounting holes are made using the mounting cut-out, the cable will not have to be disassembled to install (see provided ETVS footswitch cable assembly drawing). As always, ensure you

perform an operational check of your equipment before returning to service.

Remarks: AJW-1732, the OKC Communications Engineering Team's Voice Switching Team, has initiated a Data Manage

ment System (DMS) document change request, DOC D-AJW-110713-0024, titled "Add footswitch jack and cab le assembly drawing to TI 6650.53A Section 6" to update TI 6650.53A, Instruction Book Enhanced Terminal V oice Switch (ETVS) Volume 1, with this drawing in the next published change, which is anticipated to be rel

eased during Q4 FY14.

If you have additional information that pertains to the subject of this document we encourage you to file yo ur own T-SAP report. Information you possess may be unknown and could be accumulated with similar reports. These additional reports may contain important safety information that allows us to identify trends and i

ssues that currently are not perceived as systemic problems or reveals a perspective that has not been consi

dered.

POC Information Email Title Phone

Technical POC1: barry.foister@faa.gov 🗟 Barry Foister, Voice Switching Team (405) 954-9928

Technical POC2:

Supply POC:

## **View Attachments**

Disclaimer: Technical Operations Safety Action Program (T-SAP) Advisories contain important safety information. However, they are not directive in nature and do not supersede any directive or policy. For additional information on T-SAP, please visit our website at www.t-sap.org or call 877-360-6961