T-SAP Advisory: TSAP-15-001 Print this page

Status: Active Effective Date: 08/21/2015

Facility Information

NAS Category: Equipment: Locations: Fac ID Code:

SURVEILLANCE ASR Multiple 53AH

Event Information

Title: TCMM Power Supply Failures after Power Cycle on ASR-11

Problem: A capacitor has been identified on the bias circuit board of the power supply that may

become too resistive. These Transmitter Control and Monitor Module (TCMM) delays or failures to reinitialize can cause equipment outages after reenergizing the power supplies.

Symptom: On the ASR-11 TCMM Power Supply, a potential time delay exists, before voltages reach

operating values after reapplying power to the TCMM power supplies. Sometimes these delays are as long as 20 minutes other times, the power supplies never fully recover.

Solution: The FAA Logistics Center (FAALC) has adopted a practice since 2010 to replace the suspect

capacitors when power supplies are received from the field. These new capacitors do not age and require no routine replacement. This practice is resulting in better TCMM power supply performance. The Office of Primary Responsibility AJW147 will be releasing a

maintenance alert on this subject again.

Remarks: If you have additional information that pertains to this document, please file your own T-SA

P report. Unique information you possess could augment existing reports. This additional da ta may contain important NAS safety information that allows us to identify trends and issue s currently not perceived as systemic problems, or reveal a perspective that has not been c

onsidered.

POC InformationEmailTitlePhone

 Technical POC1:
 gary.benny@faa.gov ☒
 AJW-1471 ES
 (405) 954-0456

 Technical POC2:
 rich.kinder@faa.gov ☒
 AJW-1471 ES
 (405) 954-9591

 Supply POC:
 shawn.m.oglesby@faa.gov ☒
 AML-2000 IM-12
 (405) 954-7648

Disclaimer: Technical Operations Safety Action Program (T-SAP) Advisories contain important safety information. However, they are not directive in nature and do not supersede any directive or policy. For additional information on T-SAP, please visit our website at

www.t-sap.org or call 877-360-6961