

Tech Ops Safety Action Program (T-SAP)

[Team Login](#)[T-SAP Main](#)

T-SAP Advisory: TSAP-14-007		Email Subscribe Unsubscribe Print	
Status: Active		Effective Date: 08/13/2014	
Facility Information			
NAS Category:	Equipment:	Locations:	Fac ID Code:
ALL	RMLS	MULTIPLE	ALL
Event Information			
Title:	Peabody PM/Cert Master "Total Tasks"		
Problem:	Changing Peabody PM/Cert Master "Total Tasks" field may cause an unintended consequence in that the National Task Glossary Code (TGC) will no longer supply the Order number/paragraph reference. This contributes to incorrect logging and 6000.15 compliance issues.		
Symptom:	Lack of awareness of the effect that modifying the PM/Cert Master fields may have on logging requirements.		
Solution:	National task references may have a default "Total Tasks" of other than "1" and should not be modified unless the user has an understanding of the results. If no other fields below the task count are populated with data, the default value for this field is "1".		
Remarks:	<p>There is currently an approved NAS Change Proposal (NCP) that will mitigate the issue via a Remote Monitoring and Logging System (RMLS) software modification.</p> <p>For additional information, please contact your Service Area RMLS POC. ESA - Robert.Dove@faa.gov, (770) 210-7060 CSA - James.Fulton@faa.gov, (913) 254-8011 WSA - Donna.Lyseng@faa.gov, (510) 745-3389</p> <p>If you are an eligible T-SAP submitter and have additional information that pertains to the subject of this document, we encourage you to file your own T-SAP report. Information you possess may be unknown to the E RC and could augment existing reports. These additional reports may contain important safety information that allows us to identify trends and issues currently not perceived as systemic problems, or reveal a perspective that has not been considered.</p>		
POC Information	Email	Title	Phone
Technical POC1:			
Technical POC2:			
Supply POC:			

Disclaimer: Technical Operations Safety Action Program (T-SAP) Advisories contain important safety information. However, they are not directive in nature and do not supersede any directive or policy. For additional information on T-SAP, please visit our website at www.t-sap.org or call 877-360-6961.